



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 04/10/2018	Report number: V/38376/18/10/03	Job no: 38376
Name and Address of owner for whom the thorough examination was made: PREMIER LOGISTICS MUSCAT SULTANATE OF OMAN		Address of premises at which the examination was made: JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>KING PIN AND FILLET WELD</u>		
Make : JOST (3.5")		
Type : KZ-14		
Trailer Reg: 9097 YS		
Fleet No. : PLM-1954		
[I] shaped cylindrical king pin. Top head 114mm Intermediate 89mm Bottom head 111mm		
Qty: 1no.		
Date of Last MPI/ Cert No(If any):N/A		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Qualification : ASNT L2	Vijeesh Ravi 	Latest date by which next MPI must be carried out: 03/10/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		