

# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 04.02.2026	Report number: AT6733.26.02.03	Job no: 6733
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <u>KING PIN AND FILLET WELD</u>		
<p>Make: JOST (3.5")  Type: KZ 1016  Trailer Reg: 7188 MA  Fleet No.: TS 606  [I] shaped cylindrical king pin.  Top head 114mmØ  Intermediate 89mmØ  Bottom head 111mmØ</p> <p>Qty: 1 no</p>		
Date of Last MPI/ Cert No (If any): 24/08/2025 ( AT/5151/25/08/10)		
Result of the above test:  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature: Anoop Thankachan		Latest date by which next MPI must be carried out: 03.08.2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS</b> <b>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.</b> <b><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		