




**MAGNETIC PARTICLE INSPECTION REPORT**

Date of Thorough Examination: 01/03/2020	Report number: K/42672/20/03/01	Job no: 42672
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN	Address of premises at which the examination was made:  JUFFNAIN	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b><u>KING PIN AND FILLET WELD</u></b> Make : JOST ( 3.5") Type : KZ14 Trailer Reg: 8896 ML Fleet no: T02435 [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ  Qty: 1nos  Date of Last MPI/ Cert No( If any):N/A		
Result of the above test :  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Malik  Qualification : ASNT L2		Latest date by which next MPI must be carried out:  28/02/2021
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		