

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 23/11/2022	Report number: MP/49823/22/11/06	Job no: 49823
Name and Address of the Owner of the Equipment  TRUCK OMAN - NORTH SULTANATE OF OMAN		Address of premises at which the examination was made:  SAFAH
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE ONLY ]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	

### Description and identification of the equipment:

#### FIFTH WHEEL

Make: JOST

Type: JSK 38C

Serial no: 1663500202

Reg no: 8820 MD / TS 213

Qty: 1 no

Date of Last MPI/ Cert No( If any): 14/07/2021; MA/46788/21/07/51

Result of the above test :

**MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION**

Inspected by, Name & Signature : Koshy Mathew		Latest date by which next MPI must be carried out: 22/11/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

