



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

|                                                                                                                                                                                                                                                                                                                                |                                                                                     |                                                                                       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Date of Thorough Examination:<br>01/10/2020                                                                                                                                                                                                                                                                                    | Report number:<br>A/44702/20/10/03                                                  | Job no:<br>44702                                                                      |
| Name and Address of the Owner of the Equipment<br>TRUCK OMAN EQUIPMENT RENTAL<br>SULTANATE OF OMAN                                                                                                                                                                                                                             | Address of premises at which the examination was made:<br>H-50 YIBAL                |                                                                                       |
| Method: WET<br>Surface Condition: Acceptable                                                                                                                                                                                                                                                                                   | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke                          | Test temperature: Ambient                                                             |
| Area Inspected ( tick the appropriate box):<br><input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others                                                                                                          |                                                                                     |                                                                                       |
| WHITE CONTRAST PAINT: Magnavis WCP                                                                                                                                                                                                                                                                                             | MAGNETISING METHOD: Wet suspension black ink                                        |                                                                                       |
| BLACK MAGNETIC INK: Magnaflux 7HF                                                                                                                                                                                                                                                                                              | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1                             |                                                                                       |
| Description and identification of the equipment:<br><b><u>KING PIN AND FILLET WELD</u></b><br>Make : JOST ( 3.5")<br>Trailer Reg: 6295 MK<br>Fleet No. : PLM-825<br>[I] shaped cylindrical king pin.<br>Top head 114mmØ<br>Intermediate 89mmØ<br>Bottom head 111mmØ<br><br>Qty: 1no.<br>Date of Last MPI/ Cert No( If any):N/A |                                                                                     |                                                                                       |
| Result of the above test :<br>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION                                                                                                                                                                                                     |                                                                                     |                                                                                       |
| Inspected by, Name & Signature :<br>Koshy Mathew<br><br>Qualification : ASNT L2                                                                                                                                                                                                                                                |  | Latest date by which next MPI must be carried out:<br><br>30/09/2021                  |
| Name and address of employer of persons making and authenticating this report:<br><br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>                                                     |                                                                                     |  |

