

# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/11/2020	Report number: O/44634/20/11/01	Job no: 44364
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>KING PIN AND FILLET WELD</u> Make : JOST ( 3.5") Type : KZ 1410 Trailer Reg: 7805 AK Fleet No: PLM 827 [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ		
Qty: 1nos  Date of Last MPI/ Cert No( If any):N/A		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : Koshy Mathew  Qualification : ASNT L2		Latest date by which next MPI must be carried out: 01/11/2021
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS</b> <b>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.</b> <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

