




## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 13/09/2018	Report number: MP/37745/18/09/02	Job no: 37745
Name and Address of owner for whom the thorough examination was made:  PREMIER LOGISTICS MUSCAT SULTANATE OF OMAN	Address of premises at which the examination was made:  JIFFNAIN	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>KING PIN AND FILLET WELD</u>  Make : JOST ( 3.5")  Type : KZ 14  Trailer Reg: 9098 YS  Fleet No. : PLM 1953  [I] shaped cylindrical king pin. Top head 114mm Intermediate 89mm Bottom head 111mm  Qty: 1no.  Date of Last MPI/ Cert No( If any):N/A		
Result of the above test :  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature :  Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out:  12/09/2019
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		