



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

|                                                                                                                                                                                                                                                                        |                                                                 |                                                                  |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|------------------------------------------------------------------|
| Date of Thorough Examination:<br>14/07/2021                                                                                                                                                                                                                            | Report number:<br>MA/46788/21/07/42                             | Job no:<br>46788                                                 |
| Name and Address of the Owner of the Equipment<br>TRUCK OMAN - NORTH<br>SULTANATE OF OMAN                                                                                                                                                                              | Address of premises at which the examination was made:<br>SAFAH |                                                                  |
| Method: WET<br>Surface Condition: Acceptable                                                                                                                                                                                                                           | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke      | Test temperature: Ambient                                        |
| Area Inspected ( tick the appropriate box):<br><input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE ONLY ]                                        |                                                                 |                                                                  |
| WHITE CONTRAST PAINT: Magnavis WCP                                                                                                                                                                                                                                     | MAGNETISING METHOD: Wet suspension black ink                    |                                                                  |
| BLACK MAGNETIC INK: Magnaflux 7HF                                                                                                                                                                                                                                      | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1         |                                                                  |
| Description and identification of the equipment:<br><u>FIFTH WHEEL</u><br>Make: JOST<br>Type: JSK 38C<br>Reg no: 8462 M.D / TO 602<br><br>Qty: 1 no<br>Date of Last MPI/ Cert No( If any): N/A                                                                         |                                                                 |                                                                  |
| Result of the above test :<br>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION                                                                                                                                             |                                                                 |                                                                  |
| Inspected by, Name & Signature :<br>Vijeesh Ravi<br>Qualification : ASNT L2                                                                                                                                                                                            |                                                                 | Latest date by which next MPI must be carried out:<br>13/07/2022 |
| Name and address of employer of persons making and authenticating this report:<br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a> |                                                                 |                                                                  |

