



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 28/10/2018	Report number: MP/38530/18/10/05	Job no: 38530
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN (NORTH) SULTANATE OF OMAN	Address of premises at which the examination was made: HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☒ Weldment areas ☒ Stress Areas ☐ Full Body ☐ Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>KING PIN AND FILLET WELD</u> Make : JOST (3.5") ID No. : 2689 Trailer Reg: 849 KW [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1no. Date of Last MPI/ Cert No(If any):N/A		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out: 27/10/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		