



الشركة الفنية لخدمات السلامة ش.م.م  
SAFETY *technical* SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 23/03/2020	Report number: K/42699/20/03/01	Job no: 42699
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	

Description and identification of the equipment:

**KING PIN AND FILLET WELD**

Make : JOST ( 3.5")

Type : KZ1412

Trailer Reg: 3919MR

Owner Id: PLM 382

[I] shaped cylindrical king pin.

Top head 114mmØ

Intermediate 89mmØ

Bottom head 111mmØ

Qty: 1no

Date of Last MPI/ Cert No( If any): N/A

**Result of the above test :**

**MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION**

Inspected by, Name & Signature :OSWIN		Latest date by which next MPI must be carried out: 22/03/2021
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		