



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 28/06/2022	Report number: MO/49378/22/06/36	Job no: 49378
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: FARAH

Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
--	--	---------------------------

Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	

Description and identification of the equipment: <u>MAIN HOOK & AUX HOOK</u> <u>CRANE DETAILS</u> Make : TADANO (2015) Model no. : GR-500E-2 Serial no. : 541244 Reg. No. : 1640 HA Owner ID No. : PLM-1492 <u>HOOK DETAILS</u> Main hook Serial no. : FT 29-10-14 Aux Hook Serial no. : GIN-49-12-14 Qty: 2 Nos Date of Last MPI/ Cert No(If any): 17/08/2021 ; MA/47207/21/08/19		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Mostafa Mohamed Qualification : ASNT L2		Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

