



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 19/07/2018	Report number: MP/37719/18/07/01	Job no: 37719
Name and Address of owner for whom the thorough examination was made: PREMIER LOGISTICS SULTANATE OF OMAN	Address of premises at which the examination was made: JIFFNAIN	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>CRANE HOOK MPI</u> Crane Make : GROVE Hook Block Make : Johnson Hook Block Serial No. : 14-1889 Hook Block ID No. : 13752 Reg. No. : 3928 HA		
Qty: 1no		
Date of Last MPI/ Cert No(If any): 12/08/2015 ; MP/30116/15/08/01		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out: 18/07/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		