

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 19/11/2025	Report number: K/5096/25/11/04	Job no: 5096
Name and Address of the Owner of the Equipment TRUCKOMAN EQUIPMENT RENTAL LLC. SULTANATE OF OMAN		Address of premises at which the examination was made: CCED FARAH SITE
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnaflux WCP	MAGNETISING METHOD: Wet suspension black ink
-------------------------------------	--

BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
-----------------------------------	---

Description and identification of the equipment:

TADANO RT CRANE MAIN HOOK

Capacity: 51.0 tonnes

Serial No.: M5519

Fitted in Crane Reg. No.: 8668 HA (PLM 1497)

Date of Last MPI/ Cert No. (If any): 06/12/2024 (MN/2413/24/12/02)



Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : GERARD D. ENRIQUEZ		Latest date by which next MPI must be carried out: AFTER ONE YEAR AND OR AT THE DISCRETION OF THE LIFTING INSPECTOR
Qualification: ASNT LEVEL 2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		