



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 25/11/2018	Report number: O/38766/18/11/02	Job no: 38766
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made:  JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><b>TEST ON HOOK BLOCK</b></p> <p>Make : TADANO</p> <p>Hook Serial no. : FT-19-11-13</p> <p>Crane Model no. : GR-500EX</p> <p>Serial no. : 541084</p> <p>YOM : 2014</p> <p>Reg. No. : 4164 BA</p> <p>Owner ID No. : PLM 1490</p> <p>Qty: 1no</p>		
Date of Last MPI/ Cert No( If any): 13/01/2015		
<p><b>Result of the above test :</b></p> <p><b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b></p>		

Inspected by, Name & Signature :  Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out:  24/11/2019
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		