

Inspected at: Khazzan

Owner:	KZN LOGISTICS	Contractor:	BP
Make:	MITSUBISHI	Type:	PAJERO
Veh Reg. No:	8570 BK	Rated Capacity:	2 TON
Veh Reg. Exp:	04/05/2018	Sticker No:	L-13508
DDC Permit No:		Khazzan No :	
Exp Date:		ROP License No:	
Drive/Op Name:		Exp Date:	
Chassis no:	JMYLYV98WEJ714912	Km:	140998
Inspector:	HILAL AL JABRI	IVMS Provider:	FMSI
		Inspection Date:	09/09/2017

Ser	ITEM	P/F	Ser	ITEM	P/F
1	Position/parking lights	P	39	Fire extinguisher Exp:	P
2	Headlights	P	40	First aid kit	P
3	Brake lights	P	41	Tachygraphy or IVMS	P
4	Reflectors	P	42	Battery condition	P
5	Indicators	P	43	Fluid levels	P
6	Headlight aim	P	44	Towing hitch*	P
7	Steering control	P	45	Roof rack*	P
8	Steering system including tie rod ends	P	46	Speed limiter – kph -	P
9	Power steering	P	47	Hazard Warning Triangles x2	P
10	Suspension-general	P	48	Reverse lights	P
11	Front suspension/bearings, drive shaft	P	49	4X4 operation/function	P
12	Rear suspension/bearings	P	50	Rear head restraints	P
13	Shock absorbers	P	51	Radio / cassette operating	P
14	Engine, mounts, leaks	P	52	Transmission Mounts/Leaks	P
15	Parking brake lever	P	53	High visibility vests X2	P
16	Hand operated brake control valves	P	54	Pay Load written	P
17	Service brake control	P	55	Mudguards	P
18	Anti-lock braking systems*	P		Additional Items :	
19	Dual Air Bags*	P	56	Reverse alarm if vehicle over 6 m length	P
20	Mechanical brake components	P	57	HIAB SWL & Inspection date stencil	P
21	Hydraulic, air and vacuum systems	P	58	Annual swl exp date:	P
22	Brake performance	P	59	PLT certificate exp date:	P
23	Tyre, type, cod, press and age	P			
24	Wheels	P			
25	Seatbelts & seats/head restraints	P			
26	Windscreen, vision, 40mm max,crack,in swept area	P			
27	Horn	P			
28	Exhaust system (Brake*)	P			
29	Exhaust emissions (visual)	P			
30	Bodywork	P			
31	Mirrors	P			
32	Fuel system	P			
33	Electrical system	P			
34	Driving controls & driver Qualification	P			
35	Spare wheel(S),jack, shovel, tools and Hgh Viz Vests	P		VOR = VEHICLE OFF ROAD	
36	Rollover cage and padding	P		N/C = NOT CHECKED	
37	High intensity rear lights	P		N/F = NOT FITTED	
38	A/C unit	P		N/A = NOT APPLICABLE	

PASS	This vehicle is deemed fit to operate on BP business based on its roadworthiness condition at the time of conducting this inspection. It is the sole responsibility of the contractor to maintain the vehicle's fitness throughout the validity of the issued sticker. This fitness certificate doesn't waive the need for a pre-trip inspection & routine mechanical inspections which are the sole responsibility of the contractor.
------	--



Part 2 : Defect Information - Vehicle Safety Inspection Report



Registration No:	8570 BK	Date of Inspection:	09/09/2017
Attach to Part 1 of the safety inspection report			
In check number column use checklist number from part 1			
Repairs to be signed off by repair workshop supervisor			
VOR denotes Vehicle Off Road & not to be used until fault's are rectified			

I confirm that the above defect have been rectified & the vehicle is now in a roadworthy condition

Name of the Vehicle Inspector: HILAL AL JABRI **Telephone No:** 94462731
Date: 09/09/2017 **Employee Number:** 9032

Signature: