



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 14/05/2018	Report number: MA/37557/18/05/04	Job no: 37557
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  SAFAH
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FORKS</u>		
Serial no. : 8 (1 pair)		
Reg. No. of the Forklift : 1526 BM		
Qty: 2nos.		
Date of Last MPI/ Cert No( If any): 24/05/2017 ; V/34636		
Result of the above test :  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature :  Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out:  13/05/2019
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		