



AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST OF FORKLIFT

Certificate No: O/43347/20/05/61

Date of Inspection: 04/06/2020

Name and Address of the Owner:	TRUCK OMAN (SOUTH)
Maker & Date of Manufacture:	CATERPILLAR ; 2015
Place of Inspection:	SAFAH
Ref. Standard:	ISO 2330 BSEN 474-3/ SP 2275
Registration No. & Owner No.:	7333 DS ; TO-2538
Model No. and Serial No.:	930K ; CAT0930KLDYB00447
Running hours:	2910.7hrs.
Manufacturer's documentation:	Yes
Date of Previous inspection / cert no:	1/08/2019; MA/40777/19/07/04
Date of Next inspection:	31/01/2020
Date of Previous load test / cert no:	16/05/2017 ; L17-AA-05475-03
Date of Next load test:	15/05/2021
Availability of operations manual in cabin:	Yes
Availability of daily check report:	Yes

Description of Forklift:

Diesel powered hydraulic operated articulated Wheel Loader c/w forks SWL: 5000kgs @ 500mm load center.

Test carried out according to tabulated column

Description of test:	Test load applied	S.W.L
	In kgs	In kgs
Visual inspection & Performance test carried out.		
Max. Lifting Height: 3668 mm	5000 KG	5000 KG

Conclusion: Fit for its intended use at the time of inspection.

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature: Mr. Gishin Thomas



Inspected by, Name & Signature: Infanso Oswin



Annexure of certificate of test & thorough examination of Fork lift

Certificate No: O/43347/20/05/61

Date of Inspection: 04/06/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	S	
Masts and Back rest , carriage	S	
Forks and its extensions, slide end stopper, locks	S	
Load chain and its assemblies	NA	
Side rollers and roll over cage	NA	
Safety devices		
Battery and its connections	S	
Hydraulic system & hoses and end fittings	S	
Electrical system & Cables	S	
Cooling system	S	
Steering function	S	
All controls levers function & symbols legible	S	
Capacity plate in place and legible	S	
All gauges in cab	S	
Over head & foot guard	S	
Exhaust system	S	
Side shifting function (if applicable)	NA	
Horn, reverse alarm, rotating warning light	S	
Lights & indicators	S	
Seat and seat belts	S	
Parking brake and foot brake function	S	
Fire extinguisher	S	
MPI fork blades, date / report nr. (annually)	S	04/06/2020; O/43347
Mast disassembly (every 4 years)	NA	
General condition	S	
Display markings (SWL, tire pressure, insp. date, due date)	S	
S- Satisfactory NS-Not Satisfactory NA-Not applicable	NP-Not provided by OEM	SC- See Comments
Details of tools/equipments used: STS-LD-53; STS-LD-51.		
General comments: NONE		

Approved by, Name & Signature: Mr. Gishin Thomas



Inspected by, Name & Signature: Infanso Oswin