

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 30/11/2023	Report number: MP/53363/23/11/03	Job no: 53363
Name and Address of the Owner of the Equipment TRUCK OMAN - NORTH SULTANATE OF OMAN		Address of premises at which the examination was made: HAIMA

Method: WET Material: Carbon Steel Test temperature: Ambient
Surface Condition: Acceptable Equipment: Permanent magnet Yoke

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others [TOP SURFACE ONLY]

WHITE CONTRAST PAINT: Magnavis WCP MAGNETISING METHOD: Wet suspension black ink

BLACK MAGNETIC INK: Magnaflux 7HF ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

FIFTH WHEEL

Make: JOST

Type: JSK 38C

Serial No: 12034884

Reg no: 9609 RH / TO 2047

Qty: 1 no

Date of Last MPI/ Cert No(If any): 02/06/2023; MP/51262/23/06/15

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 29/05/2024
Qualification : ASNT L2		

Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com	
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------

