



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: [stsi@safetyoman.com](mailto:stsi@safetyoman.com), Website: [www.safetyoman.com](http://www.safetyoman.com)  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### CERTIFICATE OF THOROUGH EXAMINATION OF POWER DRIVEN WINCHES

Date of Thorough Examination: 03/11/2022	Report number: MP/49817/22/11/11	Job no: 49817
---	-------------------------------------	------------------

Name and Address of the Owner of the Equipment TRUCK OMAN NORTH SULTANATE OF OMAN	Address of premises at which the examination was made: HAIMA
---	---

#### Description and identification of the equipment:

#### TRUCK MOUNTED WINCH – BRADEN

PLANT NO: TER 1031

REG. NO. : 9343 BA

MODEL NO: HP-100 B

SERIAL NO. : 2050245

HAULING LOAD: 100,000 LBS. @ FIRST LAYER

POWER SOURCE : HYDRAULIC

STEEL WIRE ROPE : 1 1/8" X 40M

#### WIRE ROPE DETAILS

ID NO : BN44595/4

DESCRIPTION : 28MM X 50M STEEL WIRE ROPE SLING ONE END SOFT EYE TERMINATED WITH CROSBY TAIL CHAIN (1091525) FLEMISH SLICED WITH STEEL FERRULE & OTHER END TERMINATING WITH ALUMINIUM STOPPER

DATE OF INSPECTION/ CERTIFICATE NO.: 10/05/2022; MP/48912/22/05/43

Visual inspection and Functional test carried out.

Date of Previous Examination/ cert no: 10/05/2022; MP/48912/22/05/43	Date of Next Examination: 02/05/2023
Date of Previous Test/ cert no: NA	Date of Next Test: NA

Ref. Standards: BS EN 14492-1

Comments (If any): Refer Annex for Checklist.

**RESULT:** Recommended to change winch rope ASAP.

*This certificate becomes invalid if any Alteration/Major Repair and modification is done.*

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature Gishin Thomas

Inspected by, Name & Signature: MADHU PILLAI





# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: [stsi@safetyoman.com](mailto:stsi@safetyoman.com), Website: [www.safetyoman.com](http://www.safetyoman.com)  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### Annexure of Report of Thorough Examination of Power driven Winches

Certificate No: MP/49817/22/11/11

Date of Inspection: 03/11/2022

SECTION	✓	X	REMARKS
Structural Frame/Dogging Fixture	✓		
Drums/Sheaves/Pulleys	✓		
Wire Rope	✓		RECOMMEND TO CHANGE WINCH ROPE
Wire Rope Termination/ Structures	✓		
Ratchet & Pawl/Braking & Clutches	✓		
Electric Cables	X		
Hooking Devices	✓		
Operational Control Devices	✓		
General Maintenance	✓		
Name Plate/Safety Instructions	✓		
Cleanliness & Upkeep	✓		
Swivel / Boomer Chain / Accessories	X		

<b>Inspected by, Name &amp; Signature</b> <b>MADHU PILLAI</b> 	<b>Approved by, Name &amp; Signature</b> <b>Gishin Thomas</b> 	
<b>Name and address of employer of persons making and authenticating this report:</b> Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

