



آیه آی بی فینسوت اینترنشیونال و شرکانہم ش.م.م.
AIB-VINÇOTTE INTERNATIONAL & PARTNERS LLC

P.O. Box 420 • Mina Al Fahal • PC 116 • Sultanate of Oman
Tel. +968 24 565 771 • Fax +968 24 565 772 • vincotte@omantel.net.om • www.vincotte-oman.com

Belgian Head Office : Business Class Kentorenpark • Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium
Safety, quality and environmental services

Doc. No: AVI/FRM/INS/001

Page 1 of 2

CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF LORRY LOADING CRANE

Certificate No: AVI/TPI/3576/17

Date of Inspection: 06/08/2017

Name and Address of the Owner:	Premier Logistic Muscat
Maker & Year of Manufacture:	FASSI, 2015
Place of Inspection:	Ghala (Hydroline workshop)
Ref. Standard:	BS 7121-4
Registration No. & Owner No.:	Chassis no : K023715
Model and Serial No.:	F50A.0.21 & 0503-1111
Nr. of running hours and/or km read out:	370
Manufacturer document:	verified
Date of Previous inspection / cert. no:	New
Date of Next inspection :	05/08/2018
Date of Previous load test / cert. no:	New
Date of Next load test:	05/08/2021
Load Chart :	Available
Accessories certificates:	Not Applicable
Maintenance records / major repairs carried out:	New

Description of Crane: Diesel Powered hydraulic telescopic knuckle boom lorry loading crane mounted on flat bed truck, boom length is 2.3mtr to 4.9mtr, and the maximum capacity is 2270 Kgs @ 2.0mtr radius.

Description of test: Functional test and load test carried out as per tabulated column.	Boom length	Radius	Test load	Safe working load
	Mtr	Mtr	Kgs	Kgs
	2.0	2.0	NIL	2270
	3.6	3.6	1500	1300
	4.9	4.9	1000	960

Conclusion: Fit for its intended use

Inspected By: M.Asif

Signature:
Date: 06/08/2017

Authenticated By: Attaullah khan

Signature:
Date: 06/08/2017





آیه آی بی فینسوت انترناشیونال و شرکائهم ش.م.م.
AIB-VINÇOTTE INTERNATIONAL & PARTNERS LLC

P.O. Box 420 = Mina Al Fahal = PC 116 = Sultanate of Oman
Tel. +968 24 565 771 = Fax +968 24 565 772 = vincotte@omantel.net.com www.vincotte-oman.com

Belgian Head Office : Business Class Kantorenpark = Jan Olieslagerslaan 35 = 1800 Vilvoorde = Belgium
Safety, quality and environmental services

Doc. No: AVI/FRM/INS/001

Page 2 of 2

Annexure of certificate of test and thorough examination of Lorry Loading crane

Certificate No: AVI/TPI/3576/17

Date of Inspection: 06/08/2017

Description	Condition	Remarks
Safe load Indicator or Load meter /calibration verified	Not applicable	
Level indicator / Angle indicator	Satisfactory	
Battery and its connections	Satisfactory	
PTO (Power Take Off) correct operation	Satisfactory	
Telescopic boom extensions/ Boom pads/ Rope guides	Satisfactory	
Hoist winch/ Hoist drum / Correct spooling(if applicable)	Not applicable	
Hoist wire ropes and termination(if applicable)	Not applicable	
Outriggers / beams / jacks / pads	Satisfactory	
Tires / rims / wheel bolts	Satisfactory	
Swing bearing/ -wear / report	Satisfactory	New
Hook block system/Safety catch	Satisfactory	
Hook MPI, certificate no (Required every 4 yrs)	Satisfactory	New
Sheaves (Boom & Hook) (if applicable)	Not applicable	
Control levers /Wind shields / Mirrors	Satisfactory	
Over load cut off (generally Hydraulic relief value)	Satisfactory	
Over winding alarm or Anti 2 block (if applicable)	Not applicable	
All fasteners /Bolts / Safety pins	Satisfactory	
Electrical System	Satisfactory	
Hydraulic System(Hoses& fitting leakages)	Satisfactory	
Caution rotary light	Satisfactory	
Reverse Horn / Light	Satisfactory	
Fire extinguisher	Satisfactory	
General condition (structural integrity/functionality)	Satisfactory	
Display marking (SWL/tyre pressure/ insp.date/due date)	See Remarks	Not available

General comments: The equipment is safe for its intended use within the limits specified, provided there is continuous maintenance applied and qualified operators employed

Inspected By: M.Asif

Signature:
Date: 06/08/2017

Authenticated By: Attaullah khan

Signature:
Date: 06/08/2017

