

Client: TRUCK OMAN NORTH L.L.C		Report No: REQ-OMAN-2023-003424			
Contractor: None		Date of Inspection: 19.04.2023			
Project: None		Reg. No.: 9436 AK			
Site / Location: GHALA, Oman		Procedure No: L3-AST-ND-01, Rev-0.			
Serial No: 541640		Acceptance Criteria: AWS D1.1.			
Component Description: HOOK LIFTING					
Material: Carbon Steel		Construction Code: None			
Equipment Type: YM5 YOKE		Method:	Wet <input checked="" type="checkbox"/>	Dry <input type="checkbox"/>	Fluorescent <input type="checkbox"/>
Equipment Sl. No.: 18152		PWHT:	N/A <input checked="" type="checkbox"/>	Before <input type="checkbox"/>	After <input type="checkbox"/>
Lifting Capacity: N/A		Viewing Condition: Day Light			
Leg Spacing: 1" to 6"		Surface Condition: As welded & cleaned			
Contrast Paint: 161003		Surface Temp: 28 Deg C			
Magnetic Ink: 160601		Sensitivity: BC strip			
Sl. No.	ITEM	QTY	ID NO.	Observation	
1	HOOK(MAN) 51.0 T	1	TO 2566	NO RELEVANT INDICATION WAS OBSERVED, DURING THE INSPECTION.	

Astron Quality & Calibration LLC		Client / Contractor
Signature:		Next Insp. Date: 18 April 2024
Name: Saud Ali		
Qualification: ASNT LEVEL-2		
Date: 19 April 2023		

Rev No. 1

L4-AST-ND-02