




### MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 25/03/2019	Report number: MA/39827/19/03/10	Job no: 39827
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made:  SAFAH	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b><u>KING PIN AND FILLET WELD</u></b>  Make : JOST ( 3.5")  Type : KZ-14  Trailer Reg: 5392 RH  Fleet No. : TO-2695  [I] shaped cylindrical king pin. Top head 114mm Intermediate 89mm Bottom head 111mm  Qty: 1no.  Date of Last MPI/ Cert No( If any): 08/07/2018 ; V/37903		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature :  Qualification : ASNT L2	Malik Mohammed 	Latest date by which next MPI must be carried out:  24/03/2020
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		