

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 18.12.2025	Report number: AT6708.25.12.01	Job no: 6708
Name and Address of the Owner of the Equipment: TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: FAHUD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FIFTH WHEEL</u> Make: HOLLAND Model No.: FW 0165 Serial no.: M 970667 H Reg. No.: 3564 DK Owner ID: TO 777 Qty: 1no		
Date of Last MPI/ Cert No (If any): 03.07.2025 (AT4480.25.07.13)		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature: Anoop Thankachan		Latest date by which next MPI must be carried out: 17.06.2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		