

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 28/06/2022	Report number: MP/48938/22/06/28	Job no: 48938
Name and Address of the Owner of the Equipment  TRUCK OMAN (NORTH) SULTANATE OF OMAN		Address of premises at which the examination was made:  HAIMA

Method: WET      Material: Carbon Steel      Test temperature: Ambient  
Surface Condition: Acceptable      Equipment: Permanent magnet Yoke

Area Inspected ( tick the appropriate box):

Weldment areas     Stress Areas     Full Body     Others

WHITE CONTRAST PAINT: Magnavis WCP      MAGNETISING METHOD: Wet suspension black ink

BLACK MAGNETIC INK: Magnaflux 7HF      ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

FIFTH WHEEL

MAKE: SAMPA

MODEL :- SPC8D1002

SERIAL NO: 55 R – 01 .6221

OWNER ID: PLM – 1012

REG NO: 4889 YR

Qty: 1 no

Date of Last MPI/ Cert No( If any):29/06/2021 ; V/46970/14

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 27/06/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

