



الشركة الفنية لخدمات السلامة ش.م.م. SAFETY *technical* SERVICES CO. LTD.

CERTIFICATE OF THOROUGH EXAMINATION AND TEST OF LORRY LOADER

Certificate No: MP/39037/19/03/07

Date of Inspection: 06/03/2019

Name and Address of the Owner:	PREMIER LOGISTICS			
Maker & Date of Manufacture:	FERRARI ; 2018			
Place of Inspection:	NIMR			
Ref. Standard:	BS 7121-4, SP 2275			
Registration No.& Owner No.:	6483 MS ; PLM 1421			
Model and Serial No.:	F 550A1 ; 106552			
Nr. of running hours and/or km read out:	37196 kms.			
Manufacturer's documentation:	Yes			
Date of Previous inspection / cert. no:	14/03/2018 ; AVI/TPI/1522/18			
Date of Next inspection :	05/03/2020			
Date of Previous load test/ cert. no:	14/03/2018 ; AVI/TPI/1522/18			
Date of Next load test:	13/03/2022			
Availability of operations manual in cab:	Yes			
Load Chart in cab:	Near Control			
Accessories certificates:	N/A			
Availability of daily check report:	Yes			
Maintenance records / major repairs carried out:	Yes			
Description of Crane: Diesel powered, Hydraulically operated, lorry loader crane with knuckle boom Max capacity 1870 kg at 2.45m boom length & @ 2.45m radius.				
Test carried out according to tabulated column				
Description of test: (configuration of the crane at the time of inspection)	Boom length (m)	Radius (m)	Test load (kgs)	Safe working load (kgs)
Hook WLL : 3.2 t	2.45m	2.45m	1870 kg	1870 kg
	3.65m	3.65m	---	1285 kg
	5m	5m	945 kg	945 kg
Conclusion: Fit for its intended use at the time of inspection.				

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Malik Mohammed



Ref: STS-FMT-04 Rev.01 Date: 27.01.2019

1 / 2

Annexure of certificate of test & thorough examination of lorry loader crane

Certificate no: MP/39037/19/03/07

Inspection date: 07/03/2019

Description	Condition	Remarks
Safe load indicator/calibration verified(if applicable)	N/A	
Level indicator	Satisfactory	
Load chart	Satisfactory	
Battery and connections	Satisfactory	
Crane base mounting / Physical Chassis condition	Satisfactory	
PTO(Power take off) correct operation	Satisfactory	
Crane operating levers/links/markings	Satisfactory	
Telescopic boom extensions/Boom pads/Rope guides	Satisfactory	
Hydraulic cylinder condition/lock pin/ smooth function	Satisfactory	
Hoist winch/Hoist drum/Correct spooling (if applicable)	N/A	
Hoist wire rope and end terminations (if applicable)	N/A	
Outriggers/ beams / jacks / pads	Satisfactory	
Tires / rims / wheel bolts	Satisfactory	
Foot brake /Parking brake	Satisfactory	
Slew system/ mounting/functional condition	Satisfactory	
Hook block system/Safety catch	Satisfactory	
Hook MPI, certificate no (Required every 4 yrs)	N/A	
Hook	Satisfactory	
Operator cab/ Control levers /Wind shields/Mirrors	Satisfactory	
Over load cut off (hydraulic relief valve)	Satisfactory	
Over winding alarm or Anti two block (if applicable)	N/A	
All fasteners /Bolts / Safety pins	Satisfactory	
Electrical System	Satisfactory	
Hydraulic System(Hoses and fitting leakages)	Satisfactory	
Caution rotary light	Satisfactory	
Reverse Horn / Light	Satisfactory	
Fire extinguisher	Satisfactory	
General condition (structural integrity/functionality)	Satisfactory	
Display marking (SWL/tyre pressure/ insp.date/due date)	Satisfactory	
Details of tools/equipments used: Measuring tape (STS-LD-75) ; Load cell (SP 14813)		

General comments: Nil

Approved by, Name &Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Malik Mohammed





Ref: STS-FMT-04 Rev.01 Date: 27.01.2019

2 / 2

The inspection certificate shall not be reproduced except in full without the approval of the inspection body and the client.
Inspection is performed only related to the work ordered/the items or the lot inspected.
For certificate authenticity and clarifications contact us at info@safetyoman.com