



آیه آی بی فینسوت انترناشیونال و شرکائیم ش.م.م.  
AIB-VINÇOTTE INTERNATIONAL & PARTNERS LLC

P.O. Box 420 • Mina Al Fahal • PC 116 • Sultanate of Oman  
Tel. +968 24 585 771 • Fax +968 24 585 772 • vincotte@omantel.net.om • www.vincotte-oman.com

Belgian Head Office : Business Class Kantorenpark • Jan Ollelaerlaan 35 • 1800 Vilvoorde • Belgium  
Safety, quality and environmental services

Doc. No: AVI/FRM/INS/001

Page 1 of 2

**CERTIFICATE OF THOROUGH EXAMINATION OF LORRY LOADING CRANE**

Certificate No: AVI/TPI/3119/17

Date of Inspection: 10/07/2017

Name and Address of the Owner:	Truck Oman
Maker & Year of Manufacture:	Ferrari, 2015
Place of Inspection:	Misfah
Ref. Standard:	BS 7121-4
Registration No. & Owner No.:	Chassis No. K014783
Model and Serial No.:	F550A1 & 104831
Manufacturer documents :	Available
Nr. of running hours and/or km read out:	34km
Date of Previous inspection / cert. no:	New
Date of Next inspection :	09/07/2018
Date of Previous load test / cert. no:	New
Date of Next load test:	09/07/2021
Availability of operations manual:	Available
Load Chart :	Available
Accessories certificates:	Not Applicable

Description of Crane: Diesel Powered hydraulic telescopic knuckle boom lorry loading crane mounted on flatbed truck, boom length is 2.45 mtr to 5.0 mtr, the maximum capacity is 1870 Kg @ 2.45 mtr radius

Description of test: Full functional test and Load test carried out as per tabular column.	Boom length	Radius	Test load	Safe working load
	Mtr	Mtr	Kg	Kg
Load cell (if available): Calibrated load used.	2.45	2.45	Nil	1870
	5.0	5.0	1100	945

Conclusion: Fit for its intended use.

Inspected By: Attaullah khan

Signature:  
Date: 11/07/2016

Authenticated By: Anish PS

Signature:  
Date: 11/07/2017





آیه آی بی فینسوت اینترنشنال وشرکانهم ش.م.م.  
AIB-VINÇOTTE INTERNATIONAL & PARTNERS LLC

P.O. Box 420 • Mina Al Fahal • PC 116 • Sultanate of Oman  
Tel. +968 24 565 771 • Fax +968 24 565 772 • vincotte@omantel.net.om • www.vincotte-oman.com

Belgian Head Office : Business Class Kantorenpark • Jan Olieslagerlaan 35 • 1800 Vilvoorde • Belgium  
Safety, quality and environmental services

Doc. No: AVI/FRM/INS/001

Page 2 of 2

ANNEXURE OF CERTIFICATE OF THOROUGH EXAMINATION OF LORRY LOADING CRANE

Certificate No: AVI/TPI/3119/17

Date of Inspection: 10/07/2017

Description	Condition	Remarks
Safe load indicator or Load meter /calibration verified	Not applicable	
Level indicator / Angle indicator	Satisfactory	
Battery and its connections	Satisfactory	
PTO (Power Take Off) correct operation	Satisfactory	
Telescopic boom extensions/ Boom pads/ Rope guides	Satisfactory	
Hoist winch/ Hoist drum / Correct spooling(if applicable)	Not applicable	
Hoist wire ropes and termination(if applicable)	Not applicable	
Outriggers / beams / jacks / pads	Satisfactory	
Tires / rims / wheel bolts	Satisfactory	
Swing bearing/ -wear / report	Satisfactory	
Hook block system/Safety catch	Satisfactory	
Hook MPI, certificate no (Required every 4 yrs)	Not available	
Sheaves (Boom & Hook) (if applicable)	Not applicable	
Control levers /Wind shields / Mirrors	Satisfactory	
Over load cut off (generally Hydraulic relief value)	Satisfactory	
Over winding alarm or Anti 2 block (if applicable)	Not applicable	
All fasteners /Bolts / Safety pins	Satisfactory	
Electrical System	Satisfactory	
Hydraulic System(Hoses& fitting leakages)	Satisfactory	
Caution rotary light	Satisfactory	
Reverse Horn / Light	Satisfactory	
Fire extinguisher	Satisfactory	
General condition (structural integrity/functionality)	Satisfactory	
Display marking (SWL/tyre pressure/ insp.date/due date)	See remarks	To be marked

General comments: The equipment is safe for its intended use within the limits specified, provided there is continuous maintenance applied and qualified operators employed.

Inspected By: Attaullah khan

Signature:  
Date: 11/07/2017



Authenticated By: Anish PS

Signature:  
Date: 11/07/2017