

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/06/2023	Report number: MP/51262/23/06/13/	Job no: 51262
Name and Address of the Owner of the Equipment TRUCK OMAN - NORTH SULTANATE OF OMAN		Address of premises at which the examination was made: SAFAH

Method: WET Material: Carbon Steel Test temperature: Ambient
Surface Condition: Acceptable Equipment: Permanent magnet Yoke

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others [TOP SURFACE ONLY]

WHITE CONTRAST PAINT: Magnavis WCP MAGNETISING METHOD: Wet suspension black ink

BLACK MAGNETIC INK: Magnaflux 7HF ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

FIFTH WHEEL

Make: JOST

Type: JSK 38C

Reg no: 6407 BA / TO 2054

Qty: 1 no

Date of Last MPI/ Cert No(If any): 30/06/2022;MP/48939/22/06/23

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Madhu Pillai Qualification : ASNT L2		Latest date by which next MPI must be carried out: 01/12/2023
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

