

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/07/2023	Report number: A/51588/23/07/02	Job no: 51588
Name and Address of the Owner of the Equipment  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE ]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FIFTH WHEEL</u>  MAKE: JOST  TYPE: JSK38C  SERIAL NO: 13032826-63  REG NO: 4505 BK/1043		
Qty: 1 no		
Date of Last MPI/ Cert No( If any): 05/08/2021; V/46984/02		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Mohammed Anaz  Qualification : ASNT L2		Latest date by which next MPI must be carried out: 01/07/2024
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

