

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 14/09/2025	Report number: AT/5304/25/09/01	Job no: 5304
Name and Address of the Owner of the Equipment  TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <b>FIFTH WHEEL</b>  MAKE: JOST  TYPE: JSK38C  SERIAL NO: 13038618-63  REG NO: 7717 YB / TER-1046		
Qty: 1no Date of Last MPI/ Cert No (If any): MN/1560/25/02/04		
Result of the above test:  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature: ANOOP		Latest date by which next MPI must be carried out: 13/03/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS</b> <b>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.</b> <b><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		