



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

|   |  |                           |
|---|--|---------------------------|
| Date of Inspection:<br>21.01.2026   | Report number:<br>AT6731.26.01.35                                  | Job no:<br>6731           |
| Name and Address of owner for whom the thorough examination was made:<br><br>TRUCK OMAN<br>SULTANATE OF OMAN  | Address of premises at which the examination was made:<br><br>NIMR |                           |
| Method: WET<br>Surface Condition: Acceptable  | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke         | Test temperature: Ambient |
| Area Inspected (tick the appropriate box):<br><input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others  |  |                           |
| WHITE CONTRAST PAINT: Magnavis WCP  | MAGNETISING METHOD: Wet suspension black ink                       |                           |
| BLACK MAGNETIC INK: Magnaflux 7HF   | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1            |                           |
| Description and identification of the equipment:<br><b><u>KING PIN AND FILLET WELD</u></b><br><br>Make: JOST (3.5")<br>Fleet No.: TO 2448<br>Trailer Reg: 4584 ML<br>[I] shaped cylindrical king pin.<br>Top head 114mmØ<br>Intermediate 89mmØ<br>Bottom head 111mmØ<br><br>Qty: 1 no<br><br>Date of Last MPI/ Cert No (If any): 27.08.2025 (AT5203.25.08.22) |  |                           |
| Result of the above test:<br><b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>  |  |                           |

|  |  |  |
|--|--|--|
| Inspected by, Name & Signature:<br>Anoop Thankachan<br><br>Qualification: ASNT L2  |  | Latest date by which next MPI must be carried out:<br><br>20.07.2026 |
| Name and address of employer of persons making and authenticating this report:<br><br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a> |  |  |