



**MAGNETIC PARTICLE INSPECTION REPORT**

|                                                                                                                                                                                                                                                                                                                                                        |                                                                    |                                                                      |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|----------------------------------------------------------------------|
| Date of Thorough Examination:<br>04/07/2019                                                                                                                                                                                                                                                                                                            | Report number:<br>A/40291/19/07/01                                 | Job no:<br>40291                                                     |
| Name and Address of owner for whom the thorough examination was made:<br><br>TRUCK OMAN<br>SULTANATE OF OMAN                                                                                                                                                                                                                                           | Address of premises at which the examination was made:<br><br>NIMR |                                                                      |
| Method: WET<br>Surface Condition: Acceptable                                                                                                                                                                                                                                                                                                           | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke         | Test temperature: Ambient                                            |
| Area Inspected ( tick the appropriate box):<br><input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others                                                                                                                                  |                                                                    |                                                                      |
| WHITE CONTRAST PAINT: Magnavis WCP                                                                                                                                                                                                                                                                                                                     | MAGNETISING METHOD: Wet suspension black ink                       |                                                                      |
| BLACK MAGNETIC INK: Magnaflux 7HF                                                                                                                                                                                                                                                                                                                      | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1            |                                                                      |
| Description and identification of the equipment:<br><br><u><b>KING PIN AND FILLET WELD</b></u><br><br>Make : JOST ( 3.5")<br><br>Fleet No. : TO-2450<br><br>Trailer Reg: 5445 MR<br><br>[I] shaped cylindrical king pin.<br>Top head 114mmØ<br>Intermediate 89mmØ<br>Bottom head 111mmØ<br><br>Qty: 1no.<br><br>Date of Last MPI/ Cert No( If any):N/A |                                                                    |                                                                      |
| Result of the above test :<br><br>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION                                                                                                                                                                                                                         |                                                                    |                                                                      |
| Inspected by, Name & Signature :<br><br>Qualification : ASNT L2                                                                                                                                                                                                                                                                                        | Mohammed Anaz<br>                                                  | Latest date by which next MPI must be carried out:<br><br>03/07/2020 |
| Name and address of employer of persons making and authenticating this report:<br><br>SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>                                                                                                                                |                                                                    |                                                                      |