الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

# MAGNETIC PARTICLE INSPECTION REPORT

| Date of Thorough Examination: 11/08/2020 | Report number: O/44464/20/08/04 | Job no: 44464 |
|---|---|---|

| Name and Address of owner for whom the thorough examination was made: | Address of premises at which the examination was made: |
|---|---|
| TRUCK OMAN RENTAL<br>SULTANATE OF OMAN | JIFFNAIN |

**Method: WET** **Material: Carbon Steel** **Test temperature: Ambient**
**Surface Condition: Acceptable** **Equipment: Permanent magnet Yoke**

**Area Inspected ( tick the appropriate box):**

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [ TOP SURFACE]

| | |
|---|---|
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 |

**Description and identification of the equipment:**

**FIFTH WHEEL**

**MAKE: JOST**

**TYPE: JSK 38C**

**SERIAL NO: 13152613 63**

**OWNER ID: TER 1055**

**REG NO: 5632 BM**

**Qty: 1 no**

**Date of Last MPI/ Cert No( If any): N/A**

**Result of the above test :**

**MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION**

| Inspected by, Name & Signature : Koshy Mathew<br><br>Qualification : ASNT L2 | Koshy | Latest date by which next MPI must be carried out:<br><br>10/08/2021 |
|---|---|---|

**Name and address of employer of persons making and authenticating this report:**

Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS
P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.
lifting@safetyoman.com

SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED