

الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 09/01/2022	Report number: K/48159/22/01/01	Job no: 48159
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
------------------------------------	--

BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
-----------------------------------	---

Description and identification of the equipment:

KING PIN AND FILLET WELD

Make : JOST (3.5")

Type : KZ-14

Trailer Reg: 1017 Y.B / PLM 1631

[I] shaped cylindrical king pin.

Top head 114mmØ

Intermediate 89mmØ

Bottom head 111mmØ

Qty: 1nos

Date of Last MPI/ Cert No(If any): 18/08/2020;V/44227/20/08/02

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Koshy Mathew		Latest date by which next MPI must be carried out: 08/01/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

