

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 06/10/2025	Report number: MN/5326/25/10/04	Job no: 5326
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made: ADAM
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

KING PIN AND FILLET WELD

Make: JOST (3.5")

TYPE: KZ14

Trailer Reg: 3246 HM

Owner Id: TER 1626

[I] shaped cylindrical king pin.

Top head 114mmØ

Intermediate 89mmØ

Bottom head 111mmØ

Qty: 1 no

Date of Last MPI/ Cert No (If any): K/4402/25/05/05, 06/05/2025

Result of the above test:

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature: MIDHUN CS		Latest date by which next MPI must be carried out: 05/04/2026
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		