

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 24/10/2025	Report number: K/4878/25/10/10	Job no: 4878
Name and Address of the Owner of the Equipment: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: CCED
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension Black Ink
------------------------------------	--

BLACK MAGNETIC INK: Magnaflux THF	ACCEPTANCE CODE: ASME V ARTICLE T, ASTM E709, AWS D1.1
-----------------------------------	--

Description and identification of the equipment:

KING PIN AND FILLET WELD

Make: JOST (3.5")

Type: KZ14

Trailer Reg: 6195 WA

Owner Id: TER 1627

(1) shaped cylindrical king pin.

Top head 114mmØ

Intermediate 89mmØ

Bottom head 111mmØ

Qty: 1 no

Date of Last MPI Cert No (if any): N/A

Result of the above test:

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature: KOSHY MATHEW		Latest date by which next MPI must be carried out: 23/04/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. stsi@safetyoman.com		