



## MAGNETIC PARTICLE INSPECTION REPORT

|   |   |  |
|---|---|--|
| Date of Thorough Examination:<br>02/09/2019   | Report number:<br>MP/40940/19/09/44   | Job no:<br>40940   |
| Name and Address of owner for whom the thorough examination was made:<br><br>TRUCK OMAN NORTH<br>SULTANATE OF OMAN  | Address of premises at which the examination was made:<br><br>ADAM                                  |  |
| Method: WET<br>Surface Condition: Acceptable  | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke  | Test temperature: Ambient  |
| Area Inspected ( tick the appropriate box):<br><br><input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others |   |  |
| WHITE CONTRAST PAINT: Magnavis WCP  | MAGNETISING METHOD: Wet suspension black ink  |  |
| BLACK MAGNETIC INK: Magnaflux 7HF   | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1   |  |
| Description and identification of the equipment:<br><br><b>FORK HEEL AND HOLDING BRACKET</b>  |   |  |
| Owner ID No. : TO-2529  |   |  |
| Forklift Reg. No. : 5023 HA   |   |  |
| Forklift Serial no. : B00349  |   |  |
| Fork Dimension : LxWxH-1200 x 150 x 700mm   |   |  |
| Qty: 2nos.  |   |  |
| Date of Last MPI/ Cert No( If any): 31/07/2018 ; MP/37723/18/07/03  |   |  |
| Result of the above test :<br><br><b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</b>  |   |  |
| Inspected by, Name & Signature :<br><br>Qualification : ASNT L2   | Madhu Pillai<br> | Latest date by which next MPI must be carried out:<br><br>01/09/2020 |
| Name and address of employer of persons making and authenticating this report:<br><br>SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>   |                |  |