

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|---|--|
| Date of Thorough Examination: 22/05/2023 | Report number: MP/51259/23/05/01 | Job no: 51259 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN | | Address of premises at which the examination was made: SAFAH |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: MAGNAVIS WCP | MAGNETISING METHOD: WET SUSPENSION BLACK INK | |
| BLACK MAGNETIC INK: MAGNAFLUX 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>UPPER HOOKS, LOWER HOOK, HEEL & TOE</u> | | |
| Make : CATERPILLAR Owner ID No. : TO-2529 Reg. no. : 5023 HA | | |
| Qty: 1no Date of Last MPI/ Cert No(If any): 16/05/2022; GTK/49310/22/05/01 | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by, Name & Signature : Madhu Pillai Qualification : ASNT L2 |  | Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com |  | |

