



CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: MP/40152/19/03/08

Date of Inspection: 25/03/2019

Name and Address of the Owner:	TRUCK OMAN NORTH
Maker & Date of Manufacture:	CATERPILLAR ; 2015
Place of Inspection:	HAIMA
Ref. Standard:	BS ISO 2330/ BS EN 474-3/ SP 2275
Registration No. & Owner No.:	5023 HA ; TO-2529
Model No. and Serial No.:	930K ; CAT0930KLDYB00349
Running hours:	5769 hrs.
Manufacturer's documentation:	Yes
Date of Previous inspection / cert no:	10/06/2018 ; MP/37703/18/06/03
Date of Next inspection:	24/09/2019
Date of Previous load test / cert no:	12/08/15 ; V/30116/15/8/1
Date of Next load test:	11/8/2019
Availability of operations manual in cabin:	Yes
Availability of daily check report:	Yes

Description :

Diesel powered hydraulic articulated Wheel Loader c/w forks SWL: 5000kgs @ 500mm load center.

Test carried out according to tabulated column		
Description of test:	Test load applied In kgs	S.W.L In kgs
Visual inspection & Functional test carried out		
Max. Lifting Height: 3.8m	5000 kg	5000 kg
Hydraulic creep : Nil		

Conclusion: Fit for its intended use at the time of inspection.

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin





Annexure of certificate of test & thorough examination

Certificate no: MP/40152/19/03/08

Inspection date: 25/03/2019

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest , carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	N/A	
Side rollers and roll over cage	N/A	
Safety devices	Satisfactory	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & Cables	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls levers function & symbols legible	Satisfactory	
Capacity plate in place and legible	Satisfactory	
All gauges in cab	Satisfactory	
Over head & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	N/A	
Horn, reverse alarm, rotating warning light	Satisfactory	
Lights & indicators	Satisfactory	
Seat and seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
MPI fork blades, date / report nr. (annually)	Satisfactory	13/11/2018 ; O/38758
Mast disassembly (every 4 years)	N/A	
General condition	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	
Details of tools/equipments used: Vernier Caliper (STS-LD-65) ; Measuringtape (STS-LD-75)		

General comments: NONE

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

