

ROADWORTHINESS ASSURANCE STANDARD (RAS)  
AL HASHAR & COMPANY  
SAFETY INSPECTION REPORT - HGV



Owner:	Premier logistics Muscat
Fleet Number:	—
Odometer reading	011 100
Current Uer ( Ref Ind):	—
No. of PDO Spec.used	—
(For first use inspection only)	—


Vehicle type and Model:	T C B BACK HOE LOADER
Registration Number:	4258 - M.L
Inspection Date:	10 - 10 - 18
Inspected At:	AL HASHAR & Co., AZAIBA
Contract Number:	—
Contact Holder ( Ref Ind):	—

Part 1 : CHECK LIST FOR INSPECTION.

✓ - Pass   x - Fail   NA - Not Applicable.

In Status column, enter   ✓ - Pass   x - Fail  
\* = if required or applicable. Shaded box = according to contract or operational requirements.  
Numbers in italics, in second column, refer to UK Dept of Transport LGV Inspection Manual checkpoints.

01	3	Seat belts	✓
02	5	Smoke emission	✓
03	6	Road wheels and hubs	✓
04	7	Tyres, size and type	✓
05	8	Tyres: type, condition, size , pressure	✓
06	9	Side guards, under-run guards, bumpers	✓
07	10	Spare wheel, jack, tools	✓
08	11	Trailer coupling	✓
09	14	Mudguards	✓
10	15	Cab mountings	✓
11	16	Cab doors	✓
12	17	Cab floor and steps	✓
13	18	Seats	✓
14	19, 20	Bodywork, load area, headboard fixed	✓
15	22	Mirrors	✓
16	23, 24	Windscreen, glass, vision 100 mm crack max. in swept area	✓
17	25	Windscreen wipers, washers	✓
18	26	Speedometer	✓
19	27	Horn	✓
20	28	Driving Controls	✓
21	29	IVMS	✓
22	30, 31, 32	Steering wheel, column	✓
23	34	Pressure/Vacuum warning	✓
24	35	Pressure/Vacuum build up	✓
25	36	Mechanical brakes lever	✓
26	37	Service brake pedal	✓
27	38	Service brake operation	✓

 AL HASHAR & CO. Muscat - Oman Tel.: 24595481	BLACK TOP & GRADED ROADS			JAN FEB MAR APR MAY JUN JUL AUG SEP OCT NOV DEC
	INSPECTION NO: BG: 26227	REG. NO.: 4258 - M.L	CONTRACT NO.: —	
OWNER: Premier logistics	INSP DATE: 10 - 10 - 18	NEXT INSP: 09 - 10 - 19	INSPECTED BY: 	
1	20	21	22	DEC