



## REPORT OF THOROUGH EXAMINATION

Date of Thorough Examination: 19/09/2019	Report number: O/41291/19/09/03	Job no: 41291
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN	Address of premises at which the examination was made:  SAIWAN
--	--

**Description and identification of the equipment:**

**DIESEL POWERED HYDRAULICALLY OPERATED RUBBER TYRED BACK HOE**

Make : JCB

Model no. : 4CX

Serial no. : JCB4CX4WCJ266785

Reg. No. : 4258 ML

Fleet No. : PLM – 1531

YOM : 2018

Bucket Rated Capacity : 1.3m<sup>3</sup>

Running Hours : 1640 hrs.

Visual inspection and Functional test carried out.

Date of Previous Examination/ cert no: <b>26/03/2019 ; MP/40154/19/03/01</b>	Date of Next Examination: <b>18/03/2020</b>
---	--

Ref. Standards: BS EN 474 – 4

**Comments(If any): NONE**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**NONE**

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:(If none state NONE)

**NONE**

**IS THIS EQUIPMENT FIT FOR PURPOSE AT THE TIME OF INSPECTION?**

**YES**  **NO**

Inspected by, Name & Signature Infanso Oswin 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		