



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



CERTIFICATE OF THOROUGH EXAMINATION

Date of Thorough Examination: 17/02/2022	Report number: O/48229/22/02/10	Job no: 48229
---	------------------------------------	------------------

Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN	Address of premises at which the examination was made: SAIWAN
---	--

Description and identification of the equipment:

Diesel Powered Hydraulically Operated Rubber Tyred Back Hoe Loader

Make : JCB
Model no. : 4CX 14H2WM
Serial no. : JCB4CX4WCJ2667293
Reg. No. : 9776 BM
Fleet No. : PLM – 1532
YOM : 2018
Bucket Rated Capacity : 1.3m³
Bucket Id No: PLM-1532
Running Hours: 3325 Hrs

Visual inspection and Functional test carried out.

Refer other side of this certificate for the checklist.

Date of Previous Examination/ cert no: 17/08/2021; MA/47207/21/08/09	Date of Next Examination: 16/08/2022
---	---

Ref. Standards: BS EN 474-4

Comments(if any): NONE

RESULT: The above mentioned equipment was found to be in order for its intended use at the time of inspection.

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Inspected by, Name & Signature Infanso Oswin 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report:		
Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		



For certificate authenticity or for further clarifications, please contact us at stsi@safetyoman.com

A part of SAFETY technical SERVICES group



CERTIFICATE OF THOROUGH EXAMINATION

Annexure of certificate of test & thorough examination

Certificate No: O/48229/22/02/10

Date Of Inspection: 17/02/2022

Description	Condition	Remarks
General Condition	S	
Markings (Rated capacity, Insp. Dates)	S	
Manufacturer's ID/specification plate and legible	S	
Hydraulic system & hoses and fittings	S	
Electrical systems and cables	S	
Engine	S	
Battery and connections	S	
Parking brake and Foot brake function	S	
Warning signals / safety markings	S	
All control levers- function, legible markings	S	
Tires, Tracks , Nuts and Bolts	S	
Warning light / Reverse Alarm / Horn	S	
Operator cabin, Seatbelt, A.C, Housekeeping	S	
Condition of attachments and its securing's	S	Fix Missing Teeth On Bucket
Spark arrestor (if required)	NA	
Fire extinguisher	S	
S- Satisfactory NS-Not Satisfactory NA-Not applicable NP-Not provided by OEM SC- See Comments		
General comments: NONE		

