

CERTIFICATE OF TEST & THOROUGH EXAMINATION OF EARTH MOVING MACHINERY

Certificate No.: AUG18/750/C1

Date of Inspection: 14 AUGUST 2018

TYPE OF EQUIPMENT	WHEEL LOADER
NAME & ADDRESS OF CLIENT	OASIS TRADING & EQUIPMENT Co. LLC
NAME & ADDRESS OF OWNER OF THE EQUIPMENT	KHAZAN WAREHOUSE MANAGEMENT SERVICES
LOCATION	GHALA
REFERENCE STANDARD	BS EN 474-3:2006+A1:2009

REGISTRATION NUMBER	3142 YM
OWNER DISTINGUISHING NUMBER	---
MAKE	CATERPILLAR
MODEL	930K
SERIAL NUMBER	CAT0930KAP3K00559
YEAR OF MANUFACTURE	2018

DESCRIPTION : HYDRAULIC WHEEL LOADER WITH FORKS, MAXIMUM CAPACITY 5 TON @ 500 mm, DIESEL ENGINE

DETAILS OF PREVIOUS INSPECTION	BRAND NEW
DATE OF NEXT INSPECTION	13 February 2019

CONCLUSION: SATISFACTORY AT THE TIME OF INSPECTION

**This Certificate becomes invalid, if any Alteration / Repair & Modification are done.*

This is to certify that the Undersigned, a competent representative, did, attend to examine the item described herein in accordance to the aforementioned standard. At the time of examination, the said item were found to be free from crack, flows, deformation or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Name and position of person who
carried out the inspection and test:

MOHAMMED BIZWAN AHMED
INSPECTION ENGINEER



Authorized signatory authenticating
this Certificate:



This certificate/report is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Integrated Safety International Services liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Integrated Safety International Services be liable for any injury or damage to any person or occurring due negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items inspected by Integrated Safety International Services and which are covered by this certificate. This certificate/report shall not be reproduced except in the full without the approval of the inspection body and the client.

ANNEXURE OF CERTIFICATE OF TEST & THOROUGH EXAMINATION OF EARTH MOVING MACHINERY

Certificate No.: AUG18/750/C1

Date of Inspection: 14 AUGUST 2018

Description	Condition	Remarks
Tires, rims, wheel bolts and axles / Crawler tracks	SATISFACTORY	
Bucket / Attachments	SATISFACTORY	
Safety devices	SATISFACTORY	
Battery and its connections	SATISFACTORY	
Hydraulic system & hoses and end fittings	SATISFACTORY	
Electrical system & Cables	SATISFACTORY	
Cooling system	SATISFACTORY	
Steering function	SATISFACTORY	
All controls levers function & symbols legible	SATISFACTORY	
Capacity plate in place and legible	SATISFACTORY	
All gauges in cab	SATISFACTORY	
Over head & foot guard	SATISFACTORY	
Exhaust system	SATISFACTORY	
Horn, reverse alarm, rotating warning light	SATISFACTORY	
Lights & indicators	SATISFACTORY	
Seat and seat belts	SATISFACTORY	
Parking brake and foot brake function	SATISFACTORY	
Fire extinguisher	SATISFACTORY	
General condition	SATISFACTORY	
Display markings (SWL, tire pressure, insp. date, due date)	TO BE MARKED	

General comments:

NOTE:

FORKS MPI CERTIFICATE 14 AUGUST 2018 ; AUG18/750/MPI/C2

Name and position of person who
carried out the inspection and test:

MOHAMMED RIZWAN AHMED
INSPECTION ENGINEER



Authorized signatory authenticating
this Certificate:



MAGNETIC PARTICLE INSPECTION REPORT

Certificate No.: AUG18/750/MPI/C2

Date of Inspection : 14 AUGUST 2018

NAME & ADDRESS OF CLIENT	OASIS TRADING & EQUIPMENT Co. LLC
Name and Address of the Owner	KHAZAN WAREHOUSE MANAGEMENT SERVICES
Place of Inspection	GHALA

Material	CS	Surface	AS CLEANED
Thickness	VARIOUS	Technique	WET VISIBLE
Procedure Code	ASME V, Article 7	Background	MAGNAFLUX WCP 2
Acceptance Criteria	ASME VIII, Division I	Detecting Media	MAGNAFLUX 7HF
Specifications Referred	ASTM E709	Equipment Details	MAGNAFLUX YOKE (18151)

DESCRIPTION : FORKS FOR WHEEL LOADER

FORKS DETAILS		FORKLIFT DETAILS	
MAKE	: CANADA	ID NUMBER	: ---
SERIAL RIGHT FORK	: 371.2377	REGISTRATION No.	: 3142 YM
SERIAL RIGHT FORK	: 1964174	MAKE	: CATERPILLAR
		MODEL	: 930K
		SERIAL	: CAT0930KAP3K00559
		YEAR OF MANUFACTURE	: 2018

COMMENTS / RESULT :

NO LINEAR INDICATIONS FOUND ON THE CRITICAL AREAS.



VALIDITY OF THIS CERTIFICATE IS 1 YEARS FROM DATE OF INSPECTION.

Date of Previous Inspection	BRAND NEW	Date of Next Inspection	13 August 2019
-----------------------------	-----------	-------------------------	-----------------------

Name and position of person who carried out the inspection:


MOHAMMED RIZWAN AHMED
INSPECTION ENGINEER (ASNT LEVEL II)



 الجمعية العمالية للخدمات النفطية Oman Society for Petroleum Services	JSRS Supplier Code: OM104941 Member of OPAL Membership Number 869 ISO 9001:2015(QMS) Certificate No. AE16/3213	 JSRS joint supplier registration system
--	--	--

