

Inspected at: Muscat

Owner:	HAZZAN WARE HOUSE MANAGEMENT	Contractor:	KHAZZAN WARE HOUSE / BP
Make:	CAT / 2018	Type:	WHEEL LOADER
Veh Reg. No:	3142-YM	Rated Capacity:	13 TONS
Veh Reg. Exp:	31/07/2019	Sticker No:	P-17524
Plant/Op Permit No:	N/A	Khazzan No :	
Exp Date:	N/A	ROP License No:	N/A
Drive/Op Name:	N/A	Exp Date:	N/A
Ser. no:	CAT0930KAP3K00559	Km/Hrs:	4.6
Inspector:	NOOR AL-BALUSHI	3rd Party Insp Exp:	13/02/2019
		Inspection Date:	16/08/2019

Ser	ITEM	P/F	Ser	ITEM	P/F
	<b>General Items</b>			<b>Back-Hoe Loader Equipment</b>	
1	Seat belts / lap strap	P	38	Operators seat swivel mechanism	N/A
2	Operator seat - condition / adj mechanism	P	39	Back - actor boom	N/A
3	AC system , enclosed cab	P	40	Back - actor controls	N/A
4	Mirrors	P	41	Back - actor hydraulic hoses	N/A
5	Windscreen glass, vision (max 100mm crack) sun shade	P	42	Back - actor slew motor	N/A
6	Windscreen wipers / washers	P	43	Stabilizing jacks , feet , system leaks	N/A
7	Electric , gauges	P	44	Back -actor stowage for travel	N/A
8	Batteries , clamps & covers	P		<b>Tracked Equipment</b>	
9	Lights , indicators , brakes , working lights	P	45	Track frame	N/A
10	Horn	P	46	Track rollers	N/A
11	Hi-intensity lights	P	47	Track support rollers	N/A
12	Warning deacon	P	48	Track plates	N/A
13	Reverse light & alarm	P	49	Front guide rollers	N/A
14	Access ladder / steps / handrail	P	50	Drive sprockets	N/A
15	Fire Extinguisher 2Kg Exp: 14/08/2019	P	51	Final drive system / casing / motors	N/A
16	Wheels , hubs & wheel nuts	P	52	Steering controls	N/A
17	Tyres size & type	P	53	Steering brakes	N/A
18	Tyre condition , pressure & age	P	54	Parking brake	N/A
19	Engine , oil & fuel leaks	P	55	Boom pins & locking pins	N/A
20	Exhaust emission	P	56	Slew ring & locking pin (excavators)	N/A
21	Steering wheel / column	P		<b>Lifting Equipment, Forklift &amp; MEWP</b>	
22	Steering assembly , including track rod ends/ pins / bushes	P	57	SWL & inspection date on boom	P
23	Center pivot (articulated equipment)	N/A	58	Control panel & SLI (if applicable)	N/A
24	Steering lock (articulated equipment)	N/A	59	Stabilizers (if fitted )	N/A
25	Axle pivot / suspension system	P	60	Fork attachment	P
26	Transmission gearbox ,axles , hubs	P	61	Carrier frame - distortion / cracks	P
27	Braking system	P	62	Fork distortion / cracks	P
28	Parking brake	P	63	Fork adjustment system	P
29	Hydraulic system / reservoir	P		<b>Man riding platform (MEWP)</b>	
30	System control & gauges	P	64	Frame / safety rail / floor	N/A
31	Hydraulic hoses	P	65	Dead man switch function	N/A
32	Rotary coupling (cranes & excavators)	N/A	66	Operating Alarm	N/A
33	Equipment mounts, pins & bushes, pin retainers	P	67	Warning Signs	N/A
34	ROPS Cab	P	68	Fail Safe Recovery System	N/A
35	First Aid Kit	P			
36	Hazard Warning Triangle(except Tracked Veh)	P		<b>VOR = VEHICLE OFF ROAD</b>	
37	High visibility vests x2	P		<b>N/C = NOT CHECKED</b>	

PASS	This vehicle is deemed fit to operate on BP business based on its roadworthiness condition at the time of conducting this inspection. It is the sole responsibility of the contractor to maintain the vehicle's fitness throughout the validity of the issued sticker. This fitness certificate doesn't waive the need for a pre-trip inspection & routine mechanical inspections which are the sole responsibility of the contractor.
------	--

N/I

<b>Registration No:</b>	<b>3142-YM</b>	<b>Date of Inspection:</b>	<b>16/08/2018</b>
Attach to Part 1 of the safety inspection report			
In check number column use checklist number from part 1			
Repairs to be signed off by repair workshop supervisor			
VOR denotes Vehicle Off Road & not to be used until fault's are rectified			

**I confirm that the above defect have been rectified & the vehicle is now in a roadworthy condition**

**Name of the Vehicle Inspector:** NOOR AL-BALUSHI **Telephone No:** 94462607

Date: 16/8/2018 Employee Number: 9057

Digitized by srujanika@gmail.com

**Signature:**