



81855

شركة الخدمات الفنية لموارد البعـد
OVERSEAS TECHNICAL INSPECTION SERVICES LLC

Annexure of Certificate of Test & Thorough Examination of a Forklift

Identification No.: SJ/AUG20/487

Our Ref.No.: SJ 0200

Date of inspection: 22/08/2020

Date of issue : 24/08/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	✓	
Masts and Back rest , carriage	✓	
Forks and its extensions, slide end stopper, locks	✓	
Load chain and its assemblies	NA	
Side rollers and roll over cage	NA	
Safety devices	NA	
Battery and its connections	✓	
Hydraulic system & hoses and end fittings	✓	
Electrical system & Cables	✓	
Cooling system	✓	
Steering function	✓	
All controls levers function & symbols legible	✓	
Capacity plate in place and legible	✓	
All gauges in cab	✓	
Over head & foot guard	✓	
Exhaust system	✓	
Side shifting function (if applicable)	NA	
Horn, reverse alarm, rotating warning light	✓	
Lights & indicators	✓	
Seat and seat belts	✓	
Parking brake and foot brake function	✓	
Fire extinguisher	✓	
MPI fork blades, date / report nr. (annually)	✓	CERT NO- SJ/AUG20/489 (Expiry : 21/08/2021)
Mast disassembly (every 4 years)	NA	
General condition	✓	

General comments: Fit for its intended use

Approved by GM/OM/TM,

Name & signature: Jahan Pourjahangiri

Inspected by,

Name & Signature: Steven George J.



OTIS/CERT/FLT/01

Rev no. 01

Rev Date: 06.10.2019

Page 2 of 4



مستودع برود رقم ٣٩٠، مجمع الحارثي، الرمز البريدي رقم ١١٨، سلطنة عمان، الهاتف: ٢٤٥٠٤١٩٩، الفاكس: ٢٤٥٩٥٩٩٢، ص.ب: ٣٩٠، ١٨٤٤١٥٦
P.O. Box 390, Al Harthy Complex, Postal Code 118, Sultanate of Oman, Tel: 2450 4199, Fax: 2459 5992, C.R.: 1844156
E-mail: inquiry@otisoman.com, Website: www.otisoman.com