



## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 07/11/2019	Report number: O/41744/19/11/04	Job no: 41744
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made:  SAIWAN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>TEST CARRIED OUT ON FORK HEEL, TOE &amp; UPPER, LOWER HOOKS.</u>		
Make : CATERPILLAR		
Reg. No. : 3014 MB		
Owner ID No. : TO-1533		
Qty: 1 pair		
Date of Last MPI/ Cert No( If any): 13/11/2018 ; O/38758/18/11/05		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature :  Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out:  06/11/2020
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		