



الشركة الفنية لخدمات السلامة ش.م.م
SAFETY technical SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 13/11/2018	Report number: O/38758/18/11/05	Job no: 38758
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: JIFFNAIN
Method: WET Surface Condition: Acceptable		Material: Carbon Steel Equipment: Permanent magnet Yoke Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>TEST CARRIED OUT ON FORK HEEL, TOE & UPPER, LOWER HOOKS.</u>		
Make : CATERPILLAR		
Reg. No. : 3014 MB		
Owner ID No. : TO-1533		
Qty: 1 pair		
Date of Last MPI/ Cert No(If any): New		
Result of the above test : <u>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</u>		
Inspected by, Name & Signature : Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out: 12/11/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		