

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 28/06/2022	Report number: MO/49378/22/06/32	Job no: 49378
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: SAIWAN

Method: WET Material: Carbon Steel Test temperature: Ambient
Surface Condition: Acceptable Equipment: Permanent magnet Yoke

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
------------------------------------	--

BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
-----------------------------------	---

Description and identification of the equipment:

Forks heel, upper & lower hooks.

Reg. No. : 712 HM

Owner ID No. : TER 1534

Fork Serial No: 2504156 (Pair)

Qty: 1 pair

Date of Last MPI/ Cert No(If any): 17/08/2022 ; MA/47207/21/08/04

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Mostafa Mohamed Qualification : ASNT L2		Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

