



CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: O/41744/19/11/02

Date of Inspection: 07/11/2019

| | |
|---|-------------------------------|
| Name and Address of the Owner: | TRUCK OMAN EQUIPMENT RENTAL |
| Maker & Date of Manufacture: | CATERPILLAR ; 2018 |
| Place of Inspection: | SIWAN |
| Ref. Standard: | BS EN 474-3 |
| Registration No. & Owner No.: | 712 HM ; TER 1534 |
| Model No. and Serial No.: | 930K ; CAT0930KHP3K00628 |
| Running hours: | 653.5 hrs. |
| Manufacturer's documentation: | Satisfactory |
| Date of Previous inspection / cert no: | 14/05/2019 ; O/40338/19/05/03 |
| Date of Next inspection: | 06/05/2020 |
| Date of Previous load test / cert no: | 13/11/2018 ; O/38758/18/11/02 |
| Date of Next load test: | 12/11/2022 |
| Availability of operations manual in cabin: | Satisfactory |
| Availability of daily check report: | Satisfactory |

Description :

Diesel powered rubber tyred hydraulically operated articulated Wheel Loader c/w fork SWL : 5000 kgs @ 500 mm load center.

Test carried out according to tabulated column

| Description of test: | Test load applied | S.W.L |
|--|-------------------|-----------|
| | In kgs | In kgs |
| Visual inspection, Functional test & Performance test carried out. | 5000 kg | 5000 kg |
| Max. Lifting Height: 3907mm | | |
| Hydraulic creep : Nil | | |

Conclusion: Fit for its intended use at the time of inspection.

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin





Annexure of certificate of test & thorough examination

Certificate no: O/41744/19/11/02

Inspection date: 07/11/2019

| Description | Condition | Remarks |
|---|--------------|----------------------|
| Tires, rims, wheel bolts and axles | Satisfactory | |
| Masts and Back rest , carriage | Satisfactory | |
| Forks and its extensions, slide end stopper, locks | Satisfactory | |
| Load chain and its assemblies | N/A | |
| Side rollers and roll over cage | Satisfactory | |
| Safety devices | N/A | |
| Battery and its connections | Satisfactory | |
| Hydraulic system & hoses and end fittings | Satisfactory | |
| Electrical system & Cables | Satisfactory | |
| Cooling system | Satisfactory | |
| Steering function | Satisfactory | |
| All controls levers function & symbols legible | Satisfactory | |
| Capacity plate in place and legible | Satisfactory | |
| All gauges in cab | Satisfactory | |
| Over head & foot guard | Satisfactory | |
| Exhaust system | Satisfactory | |
| Side shifting function (if applicable) | N/A | |
| Horn, reverse alarm, rotating warning light | Satisfactory | |
| Lights & indicators | Satisfactory | |
| Seat and seat belts | Satisfactory | |
| Parking brake and foot brake function | Satisfactory | |
| Fire extinguisher | Satisfactory | |
| MPI fork blades, date / report nr. (annually) | Satisfactory | 07/11/2019 ; K/41388 |
| Mast disassembly (every 4 years) | N/A | |
| General condition | Satisfactory | |
| Display markings (SWL, tire pressure, insp. date, due date) | Satisfactory | |

General comments: NONE

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

