

CERTIFICATE OF TEST & THOROUGH VISUAL EXAMINATION OF FORKLIFT

Certificate No. : HITECH/TJN-2025-467/IC/032

Date of Inspection : 24/10/2025

Job Number : TJN-2025-467

Starting time of Inspection: 10.00 AM

Name & Address of the Owner :	M/S.TRUCKOMAN EQUIPMENT RENTAL LLC,SULTANATE OF OMAN		
Make & Date of Manufacture :	CATERPILLAR / 2018		
Location of Inspection :	MUKHAIZNA,SULTANATE OF OMAN		
Ref. Standard / Procedure / Specification :	ISO 22915-2 / BS EN 474-3 / BS ISO 2330		
Registration No. & Owner No. :	712 HM & TER 1534		
Model & Serial No. :	MODEL NO: 930 K / SERIAL NO: CAT0930KHP3K00628		
No.of running hours :	6896 HOURS		
Date of previous inspection / Cert. No.:	03/12/2024,OTIS/SCM/DEC24/07		
Date of next inspection :	24/04/2026		
Date of Previous Load Test Certificate No.:	03/12/2024,OTIS/SCM/DEC24/07		
Date of Next Load Test / Performance Test Due on.:	24/10/2026		
Availability OEM certificate :	IN-SERVICE EQUIPMENT		
Availability of operations manual in cab :	YES, AVAILABLE		
Availability of daily check report :	YES, AVAILABLE		
Hitech Reference Work Instruction :	HITECH-LFT-WI-009-LAPFL-05		
Measuring equipments's used :	SL NO	TOOLS DESCRIPTION	CALIBRATION DUE
	1.	FORK WEAR CALIPER SL NO: HT-FWC-01	04/02/2026
	2.	MEASURING TAPE SL NO: 035204	04/02/2026
DESCRIPTION OF EQUIPMENT:	DIESEL POWERED HYDRAULICALLY OPERATED WHEEL LOADER C/W.FORK, SWL: 5000 KGS @ 500MM LOAD CENTER.		

Description of Test: A Thorough visual, full functional test and Performance Test was carried out. Equipment was Operated and Observed thorough all of its motions. No Creep was Observed. Maxi. Lifting Height: 3900mm, Bucket Capacity: 3.7 m ³ ,Bucket SL NO.2515413 121000479560, Extension Boom SL NO.229-9714 Fork Serial No: 2504156 (Qty-01 Pair) Note: -Always refer to the manufacturer manual for safe operation of Wheel Loader. Examine the equipment before each use never exceeds the rated capacity.	Test Load Applied (In Kgs)	Safe Working Load (in Kgs)
	5000 Kgs @ 500 mm Load Center	5000 Kgs @ 500 mm Load Center

1. Conclusion: This is to certify that the above-mentioned lifting equipment were tested and thoroughly examined and found satisfactory at the time of inspection.

Date of Issue: 30/10/2025


Opal LEIB Number: LEIB373/163


Authorized Name: LAKSHMANDAS.M

Inspector Name: AKHIL LAL

Designation: TECHNICAL MANAGER (TPI)

Qualification: LIFTING INSPECTOR (NSL)

Authorized Signature: 

Inspector Signature: 



AN ISO / IEC 17020:2012 ACCREDITED INSPECTION BODY

2. ANNEXURE OF CERTIFICATE OF TEST & THOROUGH VISUAL EXAMINATION OF FORKLIFT

Certificate No. : HITECH/TJN-2025-467/IC/032

Date of Inspection : 24/10/2025

Job Number : TJN-2025-467

Starting time of Inspection: 10.00 AM

Status Legend: S-Satisfactory, NA-Not Applicable, F-Findings, CF-Critical Findings

Description	Status	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest, carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	N/A	
Bucket teeth / Adaptors / Breaker chisel	Satisfactory	
Safety Devices / Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Out rigger Jack (Hydraulic ram, Cylinder, Foot Plates)	Satisfactory	
Electrical system & cables	Satisfactory	
Cooling system / Fuel System Condition	Satisfactory	
Steering function	Satisfactory	
All controls lever's function & symbols legible	Satisfactory	
All gauges in cab	Satisfactory	
Overhead & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	N/A	
Spark arrestor (if fitted)	N/A	Spark arrestor to be fitted as per area requirement.
Operator cab / wind shields / Wipers / Mirrors	Satisfactory	
Horn, reverse alarm, rotating warning light	Satisfactory	
Light & indicators (Signal lights, Footbrake lights)	Satisfactory	
Seat & seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
Full functional Test	Satisfactory	
Rated Load test	Satisfactory	
Overload test	N/A	
MPI forks blades / date / report no (Annually)	Satisfactory	HITECH/TJN-2025-467/MT-125,DT:24/10/2025
Capacity plate in place and legible	Satisfactory	
Monthly inspection record / Maintenance records	Satisfactory	
General condition / functionality / Integrity	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	Inspe.date and next Inspe.due date to be marked

3. General comment: The equipment's is safe for its use within the limits specified, provided there is continuous maintenance applied and qualified operators employed. This Certificate covers only the existing configuration of the equipment at the time of examination. Any changes, alteration or modification shall require re-inspection or re-testing.

Date of Issue: 30/10/2025


Opal LEIB Number: LEIB373/163

Authorized Name: LAKSHMANDAS.M

Inspector Name: AKHIL LAL


Designation: TECHNICAL MANAGER (TPI)

Qualification: LIFTING INSPECTOR (NSL)

Authorized Signature: 

Inspector Signature: 





التيكنولوجيا المتطورة لخدمات الفحص ش.م.ع.
HITECH INSPECTION SERVICES L.L.C.

HI-TECH INSPECTION SERVICES L.L.C

P.O.BOX 141, AL RUSAYL, P.C. 124,
SULTANATE OF OMAN

Phone: (+968) 24449092 | 24446444 | 24449010 | 24446414

www.hitechoman.net Email: admin@hitechoman.net

AN ISO / IEC 17020:2012 ACCREDITED INSPECTION BODY

CERTIFICATE OF TEST & THOROUGH EXAMINATION OF MATERIAL HANDLING ARM

Certificate No. : HITECH/TJN-2025-467/IC/033

Date of Inspection : 24/10/2025

Job Number : TJN-2025-467


Starting Time of Inspection: 12.20 PM

Name & Address of the owner of the equipment: M/S.TRUCKOMAN EQUIPMENT RENTAL LLC,OMAN		Place of Inspection : MUKHAIZNA,SULTANATE OF OMAN	
Maker of Supplier : CATERPILLAR		Reference Standard / Procedure : BS ISO 13284 / LOLER	
Description and indentification of the equipment:		Test Load	SWL
<div><div><div>MATERIAL HANDLING ARM:-</div><div>MAKE. : CATERPILLAR</div><div>SERIAL NO. : 229-9714</div><div>MODEL NO. : 11-2450</div><div>OWNER ID NO. : TER-1534</div><div>REG.NO. : 712 HM</div><div>MPI REPORT NO. : HITECH/TJN-2025-467/MT-127</div><div>: DT:24/10/2025</div></div><div><div>Note:-</div><div>Connected to Wheel Loader Reg No:712 HM</div></div></div>		2450 KGS @ 1 st BOOM 1559 KGS @ 2 nd BOOM 426 KGS @ 3 rd BOOM	2450 KGS @ 1 st BOOM 1559 KGS @ 2 nd BOOM 426 KGS @ 3 rd BOOM
Details of test:		1. The above-mentioned equipment Load Tested and Visually inspected in accordance with the criteria outlined in the table above.	
Conclusion:		A thorough visual examination, load test, and MPI inspection were carried out. During the inspection, no visible cracks, deformations, or other irregularities were observed. Based on the results, the equipment was found to be in satisfactory condition at the time of assessment.	
Date of Last Visual Examination	Date of Next Visual Examination	Date of Last Load Test Cert.No.:	Date of Next Load Test Due on.
NOT AVAILABLE	23/04/2026	NOT AVAILABLE	23/10/2029

Date of Issue: 30/10/2025

Authorized Name: LAKSHMANDAS.M

Designation: TECHNICAL MANAGER (TPI)

Authorized Signature: 



Inspector Name: AKHIL LAL

Qualification: LIFTING INSPECTOR (LEEA/NSL)

Inspector Signature: 



This certificate becomes invalid if any Alteration / Major Repair and modification is done. The inspection carried out as per regulation 9 of lifting operations and lifting equipment regulation 1998 (LOLER 98)-UK This is to certify that the above signed HITECH Inspector, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformation or other defects. The liabilities & insurance as per HITECH Inspection Services LLC.

Issued:12/10/2025

HITECH-TPI-F-B049-LEQ-04