



## CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: O/40338/19/05/02

Date of Inspection: 13/05/2019

|   |                                |                    |
|---|--------------------------------|--------------------|
| Name and Address of the Owner:  | TRUCK OMAN EQUIPMENT RENTAL    |                    |
| Maker & Date of Manufacture:  | CATERPILLAR ; 2018             |                    |
| Place of Inspection:  | FARAH                          |                    |
| Ref. Standard:  | BS EN 474-3                    |                    |
| Registration No. & Owner No.:   | 1428 MA ; TER 1535             |                    |
| Model No. and Serial No.:   | 930K ; CAT0930KHP3K00631       |                    |
| Running hours:  | 575.4 hrs.                     |                    |
| Manufacturer's documentation:   | Satisfactory                   |                    |
| Date of Previous inspection / cert no:  | 13/11/2018 ; O/38758/18/11/06  |                    |
| Date of Next inspection:  | 12/11/2019                     |                    |
| Date of Previous load test / cert no:   | 13/11/2018 ; O/38758/18/11/06  |                    |
| Date of Next load test:   | 12/11/2022                     |                    |
| Availability of operations manual in cabin:   | Satisfactory                   |                    |
| Availability of daily check report:   | Satisfactory                   |                    |
| Description :<br>Diesel powered rubber tyred hydraulically operated articulated Wheel Loader c/w forks SWL : 5000 kgs @ 500 mm load center, |                                |                    |
| Test carried out according to tabulated column  |                                |                    |
| Description of test:  | Test load applied<br>In<br>kgs | S.W.L<br>In<br>kgs |
|   | 5000 kg                        | 5000 kg            |
| Visual inspection, Functional test & Performance test carried out.  |                                |                    |
| Max. Lifting Height: 3907mm   |                                |                    |
| Hydraulic creep : Nil   |                                |                    |
| Conclusion: Fit for its intended use at the time of inspection.   |                                |                    |

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin





Annexure of certificate of test & thorough examination

Certificate no: O/40338/19/05/02

Inspection date: 13/05/2019

| Description   | Condition    | Remarks                       |
|---|--------------|-------------------------------|
| Tires, rims, wheel bolts and axles  | Satisfactory |                               |
| Masts and Back rest , carriage  | Satisfactory |                               |
| Forks and its extensions, slide end stopper, locks  | Satisfactory |                               |
| Load chain and its assemblies   | N/A          |                               |
| Side rollers and roll over cage   | Satisfactory |                               |
| Safety devices  | N/A          |                               |
| Battery and its connections   | Satisfactory |                               |
| Hydraulic system & hoses and end fittings   | Satisfactory |                               |
| Electrical system & Cables  | Satisfactory |                               |
| Cooling system  | Satisfactory |                               |
| Steering function   | Satisfactory |                               |
| All controls levers function & symbols legible  | Satisfactory |                               |
| Capacity plate in place and legible   | Satisfactory |                               |
| All gauges in cab   | Satisfactory |                               |
| Over head & foot guard  | Satisfactory |                               |
| Exhaust system  | Satisfactory |                               |
| Side shifting function (if applicable)  | N/A          |                               |
| Horn, reverse alarm, rotating warning light   | Satisfactory |                               |
| Lights & indicators   | Satisfactory |                               |
| Seat and seat belts   | Satisfactory |                               |
| Parking brake and foot brake function   | Satisfactory |                               |
| Fire extinguisher   | Satisfactory |                               |
| MPI fork blades, date / report nr. (annually)   | Satisfactory | 13/11/2018 ; O/38758/18/11/07 |
| Mast disassembly (every 4 years)  | N/A          |                               |
| General condition   | Satisfactory |                               |
| Display markings (SWL, tire pressure, insp. date, due date)   | Satisfactory |                               |
| Details of tools/equipments used: Measuring tape (STS-LD-63) ; Vernier Caliper (STS-VC-7949) ; Anemometer (STS-LD-56) ; Tyre Pressure Gauge (STS-LD-80) ; Spirit Level (STS-SL-02). |              |                               |

General comments: NONE

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

